

Scissors lift Repair and reconstruction

Do you need components that are very expensive as original spare parts or are certain spare parts no longer manufactured? We supply you with precisely fitting reconstructions.



 Cylinder suspension renewed on both sides at the top of the inner shear



② Lower running rail inside the platform, running rail with wear strip on the running surface



③ Lower bearing with additional anti-rotation protection of the bolt



④ Lower bearing modified from DU plain bearing bush to solid bronze bush with solid lubricant



5 Lower bearing with additional anti-rotation protection of the bolt



③ Renewed bearing for the middle shear bolt



⑦ View into the inside of the scissor lift (cylinder side) after the overhaul



I New hydraulic cylinder set with centre shear bolt and bearing bolt



(9) Upper roller with new and reinforced bearing journal